FIG.1


N_2/H_2-Addition 5
Furnace Snout 1
Stripping Jets 9
Isolating Gas 4
N_2/H_2-Addition 5
Metal Strip 3
8
Coating Bath 2
Deflecting Roller 7
6